

MIDWEST AUTOMOTIVE & DIESEL

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

9696

Estimate Ref #0

Date Printed: 05/16/2018

Printed Time: 2:12 pm

Hat/Ref: 015

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 285,703

Date Written: 04/16/2018

Unit #:

Mileage Out: 285,703

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
DIESEL LOF	REPLACED ENGINE OIL AND FILTER. LUBED ALL DRI...				
Labor B	Work Requested - LUBE, OIL, AND FILTER SERVICE (DIESEL)				20.75
	Work Performed - REPLACED ENGINE OIL AND FILTER, LUBED ALL GREASED DRIVELINE COMPONENTS.				
Part 15-40	15W-40 ENGINE OIL		15.00	3.95	59.25
Part FL1995	ENGINE OIL FILTER		1.00	29.95	29.95
Job #1	CUSTOMER BOTTOMED OUT THE VEHICLE ON RAILROAD...	DAN B.			
Labor A	Work Requested - CUSTOMER BOTTOMED OUT THE VEHICLE ON RAILROAD TRACKS, CHECK FOR SUSPENSION DAMAGE				528.00
	Work Performed - FOUND RUBBER DRY ROTTED OFF OF ALL THE SUSPENSION BUMP STOPS. REPLACED ALL 4 SUSPENSION BUMP STOPS, REPLACED BOTH OVERLOAD SPRING STOPS.				
Part 1C3Z4730AA	SPRING STOP ASSEMBLY		2.00	31.39	62.78
Part YC3Z3020AA	BUMPER		2.00	92.08	184.16
Part YC3Z4730AA	BUMP STOP		4.00	22.63	90.52
Part 3251684AA	HARDWARE		6.00	14.86	89.16
Job #2	OIL LEAK ON GARAGE FLOOR AFTER SITTING FOR A ...	DAN B.			
Labor A	Work Requested - OIL LEAK ON GARAGE FLOOR AFTER SITTING FOR A WHILE				470.40
	Work Performed - DEGREASED AREA, FOUND INJECTION CONTROL PRESSURE SENSOR LEAKING AND CAUSING DAMAGE TO WIRE HARNESS. REPLACED INJECTION CONTROL PRESSURE SENSOR, REPLACED WIRE HARNESS, AND SYSTEM IS NO LONGER LEAKING				
Part 5C3Z12224A	WIRE HARNESS		1.00	98.23	98.23
Part F6TZ9F838A	ICP SENSOR		1.00	232.30	232.30
Part BK1551	SOLVENT		1.00	19.95	19.95
Job #3	ABS LIGHT COMES ON RANDOMLY	DAN B.			
Labor A	Work Requested - ABS LIGHT COMES ON RANDOMLY				345.60
	Work Performed - PERFORMED DIAGNOSIS, RETRIEVED CODE # C1155 AND C1158 FOR OPEN CIRCUIT ON LEFT FRONT ABS SPEED SENSOR. REPLACED LEFT FRONT ABS SPEED SENSOR, RECALIBRATED MODULE TO REMOVE FAULTS AND SYSTEM IS NOW OPERATING AS DESIGNED.				
Part F81Z2C204BB	LEFT FRONT SPEED SENSOR		1.00	225.67	225.67
Job #4	LOOSE WIRES ARE HANGING DOWN NEAR DRIVER PEDA...				
Labor A	Work Requested - LOOSE WIRES ARE HANGING DOWN NEAR DRIVER PEDALS				0.00

MIDWEST AUTOMOTIVE & DIESEL

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

9696

Estimate Ref #0

Date Printed: 05/16/2018

Printed Time: 2:12 pm

Hat/Ref: 015

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 285,703

Date Written: 04/16/2018

Unit #:

Mileage Out: 285,703

Written By:

DOM:

Save Old Parts: No

Work Performed - COULD NOT LOCATE ANY LOOSE WIRES UNDER THE DASH AT THIS TIME. WILL NEED TO HAVE CUSTOMER
DUPLICATE THIS CONCERN WITH TECHNICIAN

Job #5	SOME SCREWS ARE LOOSE ON	DAN B.		
	THE WINDSHIELD WIPER...			
Labor A	Work Requested - SOME SCREWS ARE LOOSE ON			96.00
	THE WINDSHIELD WIPER COWL			
	Work Performed - REPLACED ALL DAMAGED HARDWARE AND MOUNTED WINDSHIELD COWL PROPERLY			
Part N811353S100	ADJUSTING NUT	10.00	3.98	39.80
Part W705589S	PIN RETAINER	8.00	2.94	23.52
Part N811354S61	RETAINER	10.00	8.55	85.50

Job #6	VERIFY PARKING BRAKE	DAN B.		
	OPERATION			
Labor A	Work Requested - VERIFY PARKING BRAKE			0.00
	OPERATION			
	Work Performed - PARKING BRAKE IS OPERATING AS DESIGNED (NO CHARGE)			

Job #7	INSPECT FOR TIRE WEAR	DAN B.		
Labor A	Work Requested - INSPECT FOR TIRE WEAR			0.00
	Work Performed - TIRES WEAR IS GOOD AT THIS TIME (NO CHARGE)			

TIRE ROTATION	TIRE ROTATION			
Labor B	Work Requested - TIRE ROTATION			34.95

Job #8	TIRE VALVE CAPS ARE MISSING	DAN B.		
Labor A	Work Requested - TIRE VALVE CAPS ARE MISSING			0.00
	Work Performed - REPLACED TIRE VALVE CAPS (NO CHARGE)			

MIDWEST AUTOMOTIVE & DIESEL

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

9696

Estimate Ref #0

Date Printed: 05/16/2018

Printed Time: 2:12 pm

Hat/Ref: 015

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 285,703

Date Written: 04/16/2018

Unit #:

Mileage Out: 285,703

Written By:

DOM:

Save Old Parts: No

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$1,240.79

Labor: \$1,495.70

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$0.00

Supplies: \$131.32

Tax Total: \$123.49

Invoice Total: **\$2,991.30**

THANK YOU FOR YOUR BUSINESS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By _____

Date _____

Time _____