

MIDWEST AUTOMOTIVE & DIESEL

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

9398

Estimate Ref #0

Date Printed: 12/26/2017

Printed Time: 2:04 pm

Hat/Ref: 352

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 281,183

Date Written: 12/18/2017

Unit #:

Mileage Out: 281,183

Written By: JASON

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	REPLACE REAR HATCH STRUTS	DAN B.			
Labor A	Work Requested - REPLACE REAR HATCH STRUTS				38.40
	Work Performed - REPLACED REAR HATCH GLASS STRUTS				
Part YC3Z78406A10BA	HATCH LIFT STRUT		2.00	59.95	119.90
DIESEL LOF	REPLACED ENGINE OIL AND FILTER. LUBED ALL DRI...	DAN B.			
Labor B	Work Requested - LUBE, OIL, AND FILTER SERVICE (DIESEL)				20.75
	Work Performed - REPLACED ENGINE OIL AND FILTER, LUBED ALL GREASED DRIVELINE COMPONENTS.				
Part 15-40	15W-40 ENGINE OIL		15.00	3.95	59.25
Part 61734	ENGINE OIL FILTER		1.00	29.95	29.95
Job #2	REPLACE FUEL FILTER	DAN B.			
Labor A	Work Requested - REPLACE FUEL FILTER				96.00
	Work Performed - REPLACED FUEL FILTER				
Part 33818	FUEL FILTER		1.00	74.95	74.95
Job #3	ENGINE CLICKS AND WILL NOT START INTERMITTENT...	DAN B.			
Labor A	Work Requested - ENGINE CLICKS AND WILL NOT START INTERMITTENTLY				192.00
	Work Performed - VERIFIED CONCERN, PERFORMED ELECTRICAL DIAGNOSIS, FOUND STARTER PULLING 814 AMPS DUE TO INTERNAL FAILURE. REPLACED STARTER MOTOR AND SYSTEM IS NOW OPERATING AS DESIGNED.				
Part 6669SN	STARTER MOTOR ASSEMBLY		1.00	386.74	386.74
Job #4	VERIFY ENGINE BLOCK HEATER OPERATION	DAN B.			
Labor A	Work Requested - VERIFY ENGINE BLOCK HEATER OPERATION				0.00
	Work Performed - TESTED SYSTEM, FOUND BLOCK HEATER OPERATING AS DESIGNED. PULLED PLUG TO FRONT OF VEHICLE FOR CUSTOMER TO ACCESS EASILY. (NO CHARGE)				
Job #5	REAR WINDOW WASHER WILL NOT SPRAY AND WIPER W...	DAN B.			
Labor A	Work Requested - REAR WINDOW WASHER WILL NOT SPRAY AND WIPER WILL NOT SWIPE GLASS PROPERLY				96.00
	Work Performed - REPLACED CLOGGED WASHER NOZZLE, REPLACED REAR WIPER BLADE AND SYSTEM IS NOW OPERATING AS DESIGNED.				
Part F87Z17603AA	WASHER JET NOZZLE		1.00	9.62	9.62
Part 26160	REAR WIPER BLADE		1.00	24.95	24.95

MIDWEST AUTOMOTIVE & DIESEL

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

9398

Estimate Ref #0

Date Printed: 12/26/2017

Printed Time: 2:04 pm

Hat/Ref. 352

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 281,183

Date Written: 12/18/2017

Unit #:

Mileage Out: 281,183

Written By: JASON

DOM:

Save Old Parts: No

Job #6	INSTALL BATTERY	DAN B.	
	TENDER/CHARGER		
Labor A	Work Requested - INSTALL BATTERY		57.60
	TENDER/CHARGER		
Work Performed - INSTALLED BATTERY TENDER/CHARGER			
Part 0210123	BATTERY TENDER	1.00	91.99 91.99

Payment Date	Type	Method	Amount
--------------	------	--------	--------

Payment Totals:

Parts: \$797.35

Labor: \$500.75

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$0.00

Supplies: \$59.42

Tax Total: \$77.11

Invoice Total: **\$1,434.63**

THANK YOU FOR YOUR BUSINESS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By _____

Date _____

Time _____