

MIDWEST AUTOMOTIVE & DIESEL

Invoice

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

9975

Estimate Ref #0

Date Printed: 10/24/2018

Printed Time: 4:31 pm

Hat/Ref: 577

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 290,582

Date Written: 07/24/2018

Unit #:

Mileage Out: 290,582

Written By: JASON

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	FRONT AIR DEFLECTOR IS DAMAGED	DAVE J.			
Labor A	Work Requested - FRONT AIR DEFLECTOR IS DAMAGED				48.00
	Work Performed - UNSTALLED MISSING HARDWARE IN RIGHT FRONT WHEEL LINER, BUT FRONT AIR DAM WILL REQUIRE A NEW FRONT BUMPER DUE TO MOUNTING TABS BEING RUSTED OFF.				
Part W708099S439	RETAINER		6.00	9.88	59.28
Job #2	PASSENGER RUNNING BOARD LIGHT ON THE FRONT SI...	DAVE J.			
Labor A	Work Requested - PASSENGER RUNNING BOARD LIGHT ON THE FRONT SIDE OF THE RUNNING BOARD IS INOPERATIVE				144.00
	Work Performed - DISASSEMBLED RUNNING BOARD, REPLACED BULB AND REASSEMBLED BUT TRIM COVER IS DAMAGED AND NOT AVAILABLE ANY LONGER FROM FORD.				
Part 194	BULB		1.00	19.86	19.86
Job #3	PARKING BRAKE LIGHT DOES NOT COME ON INTERMIT...	DAVE J.			
Labor A	Work Requested - PARKING BRAKE LIGHT DOES NOT COME ON INTERMITTENTLY SINCE THE INSTALL OF THE SAFE DRIVE SYSTEM				144.00
	Work Performed - VERIFIED CONCERN, PERFORMED DIAGNOSIS, FOUND PARK BRAKE SWITCH SHORTED AND FAILING,, REPLACED PARK BRAKE SWITCH AND SYSTEM IS NOW OPERATING AS DESIGNED.				
Part S37027	SWITCH		1.00	97.63	97.63
Job #4	VERIFY ALL THE DASH WARNING LIGHTS AND MESSAG...	DAVE J.			
Labor A	Work Requested - VERIFY ALL THE DASH WARNING LIGHTS AND MESSAGES ARE FUNCTIONING PROPERLY				384.00
	Work Performed - PERFORMED DIAGNOSIS, DISASSEMBLED DASH TO ACCESS INSTRUMENT CLUSTER, FOUND SEVERAL CLUSTER BULBS BURNT OUT. REPLACED ALL DAMAGED BULBS, REASSEMBLED DASH AND ALL DASH LIGHTS ARE OPERATING AS DESIGNED.				
Part 3C3Z5412BD	CLUSTER BULB		5.00	14.23	71.15
Job #5	DRIVER SIDE SEAT BELT IS TWISTED	DAVE J.			
Labor A	Work Requested - DRIVER SIDE SEAT BELT IS TWISTED				28.80
	Work Performed - REPAIRED TWISTED SEAT BELT				

MIDWEST AUTOMOTIVE & DIESEL

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

9975

Estimate Ref #0

Date Printed: 10/24/2018

Printed Time: 4:31 pm

Hat/Ref. 577

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 290,582

Date Written: 07/24/2018

Unit #:

Mileage Out: 290,582

Written By: JASON

DOM:

Save Old Parts: No

Job #6	RED INTERIOR LIGHTS ON THE INSIDE OF THE SECO...	DAVE J.			
Labor A	Work Requested - RED INTERIOR LIGHTS ON THE INSIDE OF THE SECOND ROW DOORS ARE INOPERATIVE OR MISSING				48.00
Work Performed - RE-ATTACHED BROKEN DOOR REFLECTOR (NEW PART NOT AVAILABLE)					
Job #8	VERIFY FRONT LICENSE PLATE IS MOUNTED SECUREL...				
Labor A	Work Requested - VERIFY FRONT LICENSE PLATE IS MOUNTED SECURELY				0.00
Work Performed - PLATE IS SECURE					
Job #10	VERIFY BATTERY DRAW BEING CAUSED BY THE ADD O...	DAVE J.			
Labor A	Work Requested - VERIFY BATTERY DRAW BEING CAUSED BY THE ADD ON ACCESSORIES THE CUSTOMER INSTALLED				96.00
Work Performed - PERFORMED BATTERY DRAW TEST, FOUND DRAW WITHIN ACCEPTABLE RANGE AT THIS TIME.					
Job #11	INSTALL REAR LICENSE PLATE CAMERA PROVIDED BY...	DAVE J.			
Labor A	Work Requested - INSTALL REAR LICENSE PLATE CAMERA PROVIDED BY CUSTOMER				96.00
Work Performed - INSTALLED THE NEW CAMERA, BUT STILL HAVE NO REVERSE FEATURE (CUSTOMER WILL NEED TO SEE A ELECTRONICS SHOP TO COMPLETE THIS REPAIR					
Part NSHZ310	RCA ADAPTER		1.00	18.95	18.95
DIESEL LOF	REPLACED ENGINE OIL AND FILTER. LUBED ALL DRI...	DAVE J.			
Labor B	Work Requested - LUBE, OIL, AND FILTER SERVICE (DIESEL)				20.75
Work Performed - REPLACED ENGINE OIL AND FILTER, LUBED ALL GREASED DRIVELINE COMPONENTS.					
Part 15-40	15W-40 ENGINE OIL		15.00	3.95	59.25
Part FL1995	ENGINE OIL FILTER		1.00	29.95	29.95
Job #12	LUBE ALL DOOR STRIKERS, LATCHES AND HINGES	DAVE J.			
Labor A	Work Requested - LUBE ALL DOOR STRIKERS, LATCHES AND HINGES				48.00
Work Performed - LUBED ALL DOOR STRIKERS, LATCHES AND HINGES					

MIDWEST AUTOMOTIVE & DIESEL

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

9975

Estimate Ref #0

Date Printed: 10/24/2018

Printed Time: 4:31 pm

Hat/Ref: 577

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 290,582

Date Written: 07/24/2018

Unit #:

Mileage Out: 290,582

Written By: JASON

DOM:

Save Old Parts: No

Job #13

CRUISE CONTROL WOULD NOT DAVE J.

CANCEL ONE TIME

Labor A

Work Requested - CRUISE CONTROL WOULD NOT

0.00

CANCEL ONE TIME

Work Performed - PERFORMED DIAGNOSIS, COULD NOT VERIFY THIS CONCERN, VERIFIED CIRCUITS ARE GOOD ON CRUISE CONTROL SYSTEM AND BRAKE SWITCHES, NO PROBLEM FOUND AT THIS TIME. WILL NEED PROBLEM TO BE ABLE TO BE DUPLICATED TO CORRECT THIS ISSUE.

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$356.07

Labor: \$1,057.55

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$0.00

Supplies: \$65.18

Tax Total: \$37.92

Invoice Total: **\$1,516.72**

THANK YOU FOR YOUR BUSINESS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By _____

Date _____

Time _____