

MIDWEST AUTOMOTIVE & DIESEL

Invoice

1306 N. PROSPECT

Champaign, IL 61820

Shop Phone: (217) 352-7343

Fax: (217) 352-7366

Email: MIDWESTAAD@AOL.COM

3460

Estimate Ref #0

Date Printed: 11/30/2012

Printed Time: 1:22 pm

Hat/Ref: 759

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 252,823

Date Written: 11/20/2012

Unit #:

Mileage Out: 252,823

Written By: JASON

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
DIESEL LOF	REPLACED ENGINE OIL AND FILTER. LUBED ALL DRI...				
Labor B	Work Requested - LUBE, OIL, AND FILTER SERVICE (DIESEL)				0.75
	Work Performed - REPLACED ENGINE OIL AND FILTER, LUBED ALL GREASED DRIVELINE COMPONENTS.				
Part 15-40	15W-40 ENGINE OIL		15.00	3.95	59.25
Part	ENGINE OIL FILTER		1.00	29.95	29.95
<hr/>					
TIRE ROTATION	TIRE ROTATION				
Labor B	Work Requested - TIRE ROTATION				24.95
<hr/>					
Job #1	SOME FRONT COWL SCREWS LOOSE AND SOME MISSING	DAVE J.			
Labor A	Work Requested - SOME FRONT COWL SCREWS LOOSE AND SOME MISSING				0.00
	Work Performed - TIGHTENED AND THREAD LOCKED COWL RETAINERS (NO CHARGE)				
<hr/>					
Job #2	REAR VIEW MIRROR IS LOOSE				
Labor A	Work Requested - REAR VIEW MIRROR IS LOOSE				9.40
	Work Performed - TIGHTENED REAR VIEW MIRROR MOUNTING ASSEMBLY				
<hr/>					
Job #3	ENGINE IDLE IS HIGH AND NOISY				
Labor A	Work Requested - ENGINE IDLE IS HIGH AND NOISY				282.00
	Work Performed - VERIFIED CONCERN, PERFORMED EEC TESTS, RETRIEVED CODE # P0476 FOR POOR BACK PRESSURE VALVE PERFORMANCE, WHICH CAUSES POWERTRAIN MODULE TO COMMAND FUEL DELIVERY BASES ON IMPROPER READINGS. REMOVED AND DECARBONED BACK PRESSURE VALVE, CLEANED CARBON BUILD UP FROM EXHAUST BACK PRESSURE TUBE, REASSEMBLED AND RECALIBRATED POWERTRAIN CONTROL MODULE TO REMOVE FAULTS, RETESTED AND SYSTEM IS NOW OPERATING AS DESIGNED.				
Part BPC1567	SOLVENT		1.00	19.95	19.95
<hr/>					
Job #4	CUT 3 FORD PATS KEYS (CUSTOMER GOT LOCKED OU...				
Labor A	Work Requested - CUT 3 FORD PATS KEYS (CUSTOMER GOT LOCKED OUT BY THEFT SYSTEM ONCE				0.00
Part PATS155	FORD BRAND PATS KEY		3.00	25.00	75.00
<hr/>					
Job #5	DOG GATE IS DIGGING INTO THE PLASTIC COVER AT...				

MIDWEST AUTOMOTIVE & DIESEL

Invoice

1306 N. PROSPECT
 Champaign, IL 61820
 Shop Phone: (217) 352-7343
 Fax: (217) 352-7366
 Email: MIDWESTAAD@AOL.COM

3460

Estimate Ref #0
 Date Printed: 11/30/2012
 Printed Time: 1:22 pm

Hal/Ref. 759

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F
 VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 252,823

Date Written: 11/20/2012

Unit #:

Mileage Out: 252,823

Written By: JASON

DOM:

Save Old Parts: No

Labor A Work Requested - DOG GATE IS DIGGING INTO THE PLASTIC COVER AT BASE OF REARMOST SEAT AREA 94.00
 Work Performed - INSTALLED A BRACKET IN REAR OF VEHICLE TO PREVENT GATE FROM DIGGING IN

Job #6
 Sublet Work Requested - COMPLETE VEHICLE DETAIL 1.00 199.95 199.95

Job #7
 Labor A REMOVE CARGO CARRIER FROM ROOF FOLD SEATS DOW...
 Work Requested - REMOVE CARGO CARRIER FROM ROOF FOLD SEATS DOWN AND PUT IT INSIDE THE VEHICLE AFTER THE DETAIL 0.00
 Work Performed - (NO CHARGE)

Job #8
 Labor A FLUID LEAK FROM FRONT UNDER AXLE DAVE J.
 Work Requested - FLUID LEAK FROM FRONT UNDER AXLE 470.00

Work Performed - FOUND INNER AXLE SEALS LEAKING CAUSING FRONT DIFFERENTIAL TO LOSE FLUID. REMOVED FRONT AXLES, REPLACED INNER SEALS IN FRONT DIFFERENTIAL, REPLACED DIFFERENTIAL FLUID AND RESEALED DIFFERENTIAL COVER. LEAK IS NO LONGER PRESENT.

Part	Description	Qty	Unit Price	Total Price
75140	AXLE FLUID	3.00	24.95	74.85
F81Z1S175HCA	SEAL	2.00	34.85	69.70
2C3Z3245AA	SEAL	2.00	64.88	129.76
F81Z3254CB	SEAL	2.00	59.87	119.74
F81Z3T695AA	GUIDE	2.00	18.42	36.84
F81Z4A322AA	GASKET	2.00	9.64	19.28
4C3Z1K106AA	O-RING	2.00	29.94	59.88

Job #9
 Labor A ENGINE AIR FILTER CLOGGING DAVE J.
 Work Requested - ENGINE AIR FILTER CLOGGING 18.80
 Work Performed - REPLACED ENGINE AIR FILTER ELEMENT
 Part R88728 AIR FILTER ELEMENT 1.00 39.95 39.95

Job #10
 Labor A HOWL NOISE FROM LEFT FRONT WHILE DRIVING DAVE J.
 Work Requested - HOWL NOISE FROM LEFT FRONT WHILE DRIVING 235.00
 Work Performed - FOUND LEFT FRONT WHEEL BEARING/HUB WORN CAUSING NOISE. REPLACED LEFT FRONT WHEEL BEARING/HUB ASSEMBLY, REASSEMBLED AND NOISE IS NO LONGER PRESENT
 Part 515020 LEFT FRONT WHEEL HUB/BEARING 1.00 488.86 488.86

MIDWEST AUTOMOTIVE & DIESEL

1306 N. PROSPECT
 Champaign, IL 61820
 Shop Phone: (217) 352-7343
 Fax: (217) 352-7366
 Email: MIDWESTAAD@AOL.COM

Invoice

3460

Estimate Ref #0
 Date Printed: 11/30/2012
 Printed Time: 1:22 pm

Hat/Ref: 759

MIDWEST AUTOMOTIVE & DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F
 VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 252,823

Date Written: 11/20/2012

Unit #:

Mileage Out: 252,823

Written By: JASON

DOM:

Save Old Parts: No

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$1,223.01

Labor: \$1,134.90

Sublet: \$199.95

Misc: \$0.00

Hazmat: \$0.00

Supplies: \$113.40

Tax Total: \$116.93

Invoice Total: \$2,788.19

THANK YOU FOR YOUR BUSINESS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By _____

Date _____

Time _____