

**MIDWEST AUTOMOTIVE & DIESEL**

Invoice

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

6852

Estimate Ref #0

Date Printed: 08/10/2015

Printed Time: 3:27 pm

Hat/Ref: 296

MIDWEST AUTOMOTIVE &amp; DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 266,916

Date Written: 07/22/2015

Unit #:

Mileage Out: 266,916

Written By: JASON

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Job #1	REPLACE BULBS IN ALL EXTERIOR LIGHTS	DAVE J.			
Labor A	Work Requested - REPLACE BULBS IN ALL EXTERIOR LIGHTS				188.00
	Work Performed - REPLACED EVERY EXTERIOR LIGHT BULB ON THE VEHICLE AND ONE TURN SIGNAL SOCKET.				
Part HP4200	SOCKET		1.00	14.60	14.60
Part 9007	HEADLAMP BULB		2.00	14.95	29.90
Part BP9145	BULB SET		1.00	49.95	49.95
Job #2		DAVE J.			
Sublet	Work Requested - REPLACE CRACKED WINDSHIELD		1.00	379.95	379.95
Job #3	FRONT WINDSHIELD WIPERS MISS THE GLASS IN THE...	DAVE J.			
Labor A	Work Requested - FRONT WINDSHIELD WIPERS MISS THE GLASS IN THE MIDDLE				9.40
	Work Performed - REPLACED WIPER BLADES WITH PROFILE STYLE BLADES				
Part A20M	PROFILE WIPER BLADE		2.00	24.95	49.90
Job #4		DAVE J.			
Sublet	Work Requested - TINT REAR WINDOWS		1.00	395.00	395.00
Job #5	FRONT WINDSHIELD COWL IS LOOSE	DAVE J.			
Labor A	Work Requested - FRONT WINDSHIELD COWL IS LOOSE				28.20
	Work Performed - FASTENED FRONT COWL ASSEMBLY				
Job #6	INSTALL MOUNT FOR COMPUTER COMPONENT ON THE D...	DAVE J.			
Labor A	Work Requested - INSTALL MOUNT FOR COMPUTER COMPONENT ON THE DASH				9.40
Part H1502	HARDWARE		1.00	5.95	5.95
Job #7	MOUNT POWER INVERTER BEHIND CENTER CONSOLE	DAVE J.			
Labor A	Work Requested - MOUNT POWER INVERTER BEHIND CENTER CONSOLE				94.00
	Work Performed - FABRICATED A BRACKET AND MOUNTED INVERTER				

**MIDWEST AUTOMOTIVE & DIESEL**

Invoice

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

6852

Estimate Ref #0

Date Printed: 08/10/2015

Printed Time: 3:27 pm

Hat/Ref: 296

MIDWEST AUTOMOTIVE &amp; DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 266,916

Date Written: 07/22/2015

Unit #:

Mileage Out: 266,916

Written By: JASON

DOM:

Save Old Parts: No

Part	Description	Quantity	Unit Price	Total Price
H15524	HARDWARE / BRACKET	1.00	35.76	35.76

**Job #8** **MOVE AND RE-MOUNT LICENSE** **DAVE J.****PLATE CAMERA**

Labor A Work Requested - MOVE AND RE-MOUNT LICENSE 28.20

**PLATE CAMERA**

Work Performed - REPAIRED DAMAGED CAMERA BRACKET AND RELOCATED THE CAMERA

**ROTATE AND BALANCE****Rotate and Balance 4 tires****DAVE J.**

Misc Rotate &amp; Balance Work Requested - Rotate and Balance 4 tires 1.00 49.95 49.95

**Job #9** **INSTALL AN EXHAUST TIP COVER** **DAVE J.**

Labor A Work Requested - INSTALL AN EXHAUST TIP COVER 94.00

Work Performed - INSTALLED CHROME TIP TO COVER RUSTED EXHAUST, REPAIRED EXHAUST PIPE WHERE IT WAS SEPARATED FROM THE MUFFLER

Part 114568748 EXHAUST COLLECTOR TIP KIT 1.00 195.87 195.87

**Job #10** **RE-ATTACH TAIL GATE TRIM** **DAVE J.**

Labor A Work Requested - RE-ATTACH TAIL GATE TRIM 47.00

Work Performed - ATTACHED GATE TRIM

Part H15549876 HARDWARE 1.00 8.95 8.95

**Job #11** **MULTI-POINT VEHICLE INSPECTION** **DAVE J.**

Labor A Work Requested - MULTI-POINT VEHICLE INSPECTION 9.40

Work Performed - FOUND RADIATOR CAP LEAKING. REPLACED RADIATOR CAP

Part 17167 RADIATOR CAP 1.00 14.97 14.97

**Job #12** **DAVE J.**

Sublet Work Requested - COMPLETE VEHICLE DETAIL 1.00 229.95 229.95

**Job #13** **KEY WILL STICK IN IGNITION WHILE** **DAVE J.****ATTEMPTING T...**

Labor A Work Requested - KEY WILL STICK IN IGNITION WHILE ATTEMPTING TO START VEHICLE. 235.00

Work Performed - VERIFIED CONCERN, FOUND IGNITION LOCK CYLINDER WORN. REMOVED STEERING COLUMN, REPLACED IGNITION LOCK CYLINDER, CODED NEW CYLINDER TO MATCH EXISTING KEYS, REASSEMBLED COLUMN AND SYSTEM IS NOW OPERATING AS DESIGNED.

Part 1L3Z11582A IGNITION CLOCK CYLINDER 1.00 149.33 149.33

**MIDWEST AUTOMOTIVE & DIESEL**

2402 NORTH SHORE DR.

Urbana, IL 61802

Shop Phone: (217) 352-7343

Fax: (217) 337-3011

Email: MIDWESTAAD@AOL.COM

Web Address: MIDWESTAAD.COM

Invoice

6852

Estimate Ref #0

Date Printed: 08/10/2015

Printed Time: 3:27 pm

Hat/Ref: 296

MIDWEST AUTOMOTIVE &amp; DIESEL

Time Promised:

2001 FORD EXCURSION LIMITED V8 7.3L 445CID FI DIESEL T F

VIN: 1FMSU43F11EB99192

License: N363138

Mileage In: 266,916

Date Written: 07/22/2015

Unit #:

Mileage Out: 266,916

Written By: JASON

DOM:

Save Old Parts: No

Job #14

CRUISE CONTROL WILL NOT

DAVE J.

CANCEL BY PRESSING TH...

Labor A

Work Requested - CRUISE CONTROL WILL NOT

267.90

CANCEL BY PRESSING THE BRAKE

Work Performed - VERIFIED CONCERN, PERFORMED SYSTEM DIAGNOSTIC TESTS, FOUND CRUISE SWITCH AT BRAKE MASTER CYLINDER SHORTED. REPLACED SWITCH, RE TESTED AND SYSTEM IS NOW OPERATING AS DESIGNED.

Part BWDCCS1

CRUISE / BRAKE SWITCH

1.00

71.14

71.14

Payment Date

Type

Method

Amount

Payment Totals:

Parts: \$626.32

Labor: \$1,010.50

Sublet: \$1,004.90

Misc: \$49.95

Hazmat: \$0.00

Supplies: \$84.35

Tax Total: \$63.96

Invoice Total: **\$2,839.98**

THANK YOU FOR YOUR BUSINESS

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Authorized By \_\_\_\_\_

Date \_\_\_\_\_

Time \_\_\_\_\_